


Installation

REMOTE MOUNT METER WIRING DIAGRAM CORRECTION

This remote mount meter wiring diagram replaces the diagram in the Installation section of the Model 3051S Series Pressure Transmitter Family manual, document number 00809-0100-4801. Twenty-two gage wire is recommended for PWR connections.

Figure 1-1. Remote Mount Meter wiring diagram



Manual Supplement

00809-0300-4801, Rev AA

March 2002

Model 3051S Series

*Rosemount and the Rosemount logotype are registered trademarks of Rosemount Inc.
PlantWeb is a registered trademark of one of the Emerson Process Management group of companies.
All other marks are the property of their respective owners.*

Emerson Process Management

Rosemount Inc.

8200 Market Boulevard
Chanhassen, MN 55317 USA
T (U.S.) 1-800-999-9307
T (International) (952) 906-8888
F (952) 949-7001

www.rosemount.com



Fisher-Rosemount GmbH & Co. Fisher-Rosemount Singapore Pte Ltd.

Shipping Address:
Argelsrieder Feld 3
82234 Wessling
Germany
Tel 49 (8153) 9390
Fax 49 (8153) 939172

1 Pandan Crescent
Singapore 128461
Tel (65) 777-8211
Fax (65) 777-0947



EMERSON[™]
Process Management