

Main Identity

From: "Northpointe Hydro-Electric Plant (Callback#: 5959586)" <username@userdomain.com>
To: <RACO Group>
Cc: <username2@userdomain.com>; <username etc@userdomain.com>

Sent: Wednesday, August 13, 2003 10:13 AM
Subject: STATUS REPORT



STATUS REPORT

Channel Status Summary Counts	Total	Linked to this Destination
Unacknowledged Alarms	0	0
Acknowledged Alarms	3	3
Alarms Now Normal	0	0
Acknowledged Alarms Now Normal	0	0
Total Currently Not Normal	3	3

Cumulative Statistics	Total	Last 24 Hours
AC Power Failures	0	0
Phone Line Failures	0	0
Modbus Network Failures	2	2
Log File Events Lost	0	0
Incoming Calls	54	48
Outgoing Calls	52	52
Alarms	58	36
Alarm Acknowledgments	7	6

AC power is currently **ON**
 The battery is currently **CHARGED**.

Settled Turbidity reading is 252 NTU NORMAL
 CHANNEL 2 reading is OPEN status only
 Effluent #1 reading is 182 NTU status only
 Effluent #2 reading is 9.87 NTU status only
 Bailey Pump is running NORMAL
 RAW CL2 reading is 150 PPM **HIGH SETPOINT ALARM, ACKNOWLEDGED**
 Finished CL2 reading is 31 PPM NORMAL
 PH level is 0 pH **LOW SETPOINT ALARM, ACKNOWLEDGED**
 Tank level is b1100 1100 1100 1111 feet NORMAL
 Bailey pump reading is 17502 GPM **HIGH SETPOINT ALARM, ACKNOWLEDGED**

This email is confidential and intended solely for the addressee. If you have received it in error please [notify your Catalyst system manager](#).

As originally sent, this email and all attachments were known to be virus free. [RACO Mfg & Eng Co, Inc](#) accepts no liability for any damage caused by any virus transmitted with this email.

Need help? Try Catalyst technical support online. [Click here.](#)

Check availability of free Catalyst/Alarmware upgrades. [Click here.](#)

Check the warranty status of your Catalyst. [Click here.](#)
